

Smoke ventilator fan failure - E08000.10 / E08000.08



The E08000.10 / E08000.08 alarm appears on Rika pellet stoves when the set rotation speed for the flue fan is not reached (revolutions per minute).

Solution

Acknowledge the error message and try restarting the stove

If that does not work, the appliance needs to be inspected. It is possible that a foreign object is preventing the component from functioning properly.