Pressure switch not enough vacuum - E4000.02



The E4000.02 alarm appears on Rika pellet stoves when the pressure difference between the installation room and the combustion chamber is insufficient to resume operation.

Solution

Check the stove for air leaks (firebox door, cleaning flap), disturbances in the room where the stove is installed (exhaust hood running, closed windows, etc.), and/or the chimney draft.

If the error message cannot be cleared, a technician must be called.