Uncalibrated Pressure Sensor - E2000.10



The E2000.10 alarm (DAR system) appears on Rika pellet stoves when the pressure sensor's calibration value is no longer valid.

Solution

1. Follow the on-screen instructions exactly to restore the calibration
2. Do not close the door until the calibration is complete: the sensor calibrates with the door open

If the message persists or the error reoccurs, a technician must be contacted.