
Horizontal Motor Failure - E0800.04



The E0800.04 alarm appears on Rika pellet stoves when a malfunction in the horizontal motor (feed screw) is detected.

Solution

1. Acknowledge the error message

If the error reappears, a technician must be called.