

# Limiter / Overheated stove - E00020000.10 / E00020000.08



The E00020000.10 / E00020000.08 alarm appears on Rika pellet stoves when there is excessive heat buildup inside the unit due to insufficient convection.

## Solution

1. Let the stove cool down
2. Disconnect the power supply
3. Check that all convection and air vents are unobstructed

Depending on the model:

1. Check the operation of the convection blower in control mode
2. In the menu, SETTINGS -> MULTIAIR FAN, set the fan speed and power to AUTO
3. Unlock/press the safety thermostat button on the back of the stove