

A16 alarm

The A16 alarm appears on MCZ pellet stoves when there is insufficient water pressure.

Resolution

Add pressure to the system according to the instructions of your sanitary fitter. For the MCZ product range, the cold pressure should be 1.5 bar